

Work Order ID 149147

Tuesday, July 19, 2016 2:41:17 PM

149147

Page 1

Item ID: D4635-044

Accept

N900040100

Setup Start

NS1

Revision ID:

Stop

NS2

Item Name: Aft Ceiling Panel Assembly, RH

Start Date: 7/6/2016 Start Qty: 1.00

1

Cust Item ID:

Required Date: 7/19/2016 Req'd Qty: 1.00

1

Customer:

Reference:

DAS

21

9-89

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

NR1

QC:

Date:

JUL 20 2016

SPC (Y/N):

Date:

Stop

NR2

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

D4635

F

100

0.00

100

HandThermo

Memo

0.00

Hand Finishing Thermoforming

Pick Kit

AUG 29 2016

DAS

6

9-89

110

0.00

110

Small Fab

Memo

0.16

Small Fab

1- Assemble as per Dwg D4635-044

2-Install speaker

3- Install Air valve

4-Install Wiring Harness

5-Install wiring harness

DAS
27
9-89

NOV 03 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐																																																													
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval 																																																									
Description Work Order Deviation				Disposition																																																													
								Completed By																																																									
								Lead hand / Supervisor Approval Verification																																																									
								QC / QA Coordinator Approval																																																									
Root Cause		FAULT CATEGORY																																																															
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐	Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐	Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐	Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐	Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐	Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐	Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐	Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐	LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐	Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐	Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____			
Misidentified ☐	Past Due ☐																																																																

Work Order ID 149147

Tuesday, July 19, 2016 2:41:17 PM

149147

Page 2

Item ID: D4635-044 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Aft Ceiling Panel Assembly, RH
Start Date: 7/6/2016 Start Qty: 1.00 ***1*** Cust Item ID:
Required Date: 7/19/2016 Req'd Qty: 1.00 ***1*** Customer:
Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
120	QC5- Inspect part completeness to step on W/O	0.00							DAS 9 9-89
120									
QC	Memo	0.00							
Quality Control									
130	Identify as per dwg & Stock Location: _____	0.00							
130									DAS 27 9-89
Packaging	Memo	0.00							
Packaging									
140	QC21- Final Inspection - Work Order Release	0.00							
140									
QC	Memo	0.02							
Quality Control									

NOV 22 2016

16/11/22

DAS
21
9-89

NOV 22 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐																																																													
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval																																																										
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval																																																									
Root Cause		FAULT CATEGORY																																																															
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐	Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐	Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐	Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐	Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐	Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐	Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐	Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐	LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐	Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐	Past Expiry Date ☐	Manufacturing Process ☐	OTHER :			
Misidentified ☐	Past Due ☐																																																																

Picklist Print

Tuesday, July 19, 2016 2:41:16 PM

Page 1

Work Order ID: 149147

149147

Parent Item: D4635-044

D4635-044

Parent Item Name: Aft Ceiling Panel Assembly, RH

Start Date: 7/6/2016

Required Date: 7/19/2016

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev. A 12/08/09 New Issue DL
12/11/08 Doc Release DL
Update 13/07/09 DL verf:DD
13/12/09 DL
Ipp Rev. E Dwg Update 14/01/09 DL
Dwg. Update 15/01/27 DL

IPP Rev B
IPP Rev. C Dwg.
IPP Rev D Dwg Update
IPP Rev. F

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4635-144 *D4635-144* Aft Ceiling Replacement Panel Assembly, RH		Manufactured	No		W/O 149101	100	Each	0.0000	1	1	DAS 27 9-89	NOV 03 2016	
D4646-1 *D4646-1* Plenum Cap Assembly		Manufactured	No			100	Each	63.0000	1	1	**		

AUG 29 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : _____					

Picklist Print

Tuesday, July 19, 2016 2:41:16 PM

Work Order ID: 149147

149147

Parent Item: D4635-044

D4635-044

Parent Item Name: Aft Ceiling Panel Assembly, RH

Start Date: 7/6/2016

Required Date: 7/19/2016

Start Qty: 1.00

Required Qty: 1.00

D4708-9

Manufactured No

100

Each

23.0000

1

1

D4708-9

Lanyard

DAS

6

9-89

Location

Loc Qty

Loc Code

MF004

23

111242

1

112122

22

D4728-046

Manufactured No

100

Each

19.0000

1

1

D4728-046

RH Cabin Speaker #3

DAS

6

9-89

Location

Loc Qty

Loc Code

MF002

4

117928

4

MF009

15

124239

15

D4743-1

Manufactured No

100

Each

20.0000

1

1

D4743-1

Speaker Grill

DAS

6

9-89

Location

Loc Qty

Loc Code

MF005

20

129268

20

MS21044-N08

Purchased No

100

Each

155.0000

4

4

MS21044-N08

Nut

DAS

6

9-89

Location

Loc Qty

Loc Code

ST302

152

m131452

152

ST303

3

m127813

2

m130297

1

AUG 29 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐					

Picklist Print

Tuesday, July 19, 2016 2:41:16 PM

Work Order ID: 149147

149147

Parent Item: D4635-044

D4635-044

Parent Item Name: Aft Ceiling Panel Assembly, RH

Start Date: 7/6/2016

Required Date: 7/19/2016

Start Qty: 1.00

Required Qty: 1.00

MS21919-WDG8 Purchased No

100 Each 54.0000 3 3

MS21919-WDG8

DAS
6
9-89

Clamp

Location Loc Qty Loc Code

ST293 54

m128057 54

3

MS24693-BB51 Purchased No

100 Each 519.0000 4 4

MS24693-BB51

DAS
6
9-89

Screw

Location Loc Qty Loc Code

ST288 519

m128057 519

4

NAS1149DN832J Purchased No

100 Each 561.0000 4 4

NAS1149DN832.J

DAS
6
9-89

Washer

Location Loc Qty Loc Code

CA 84

M129499 84

ST264 477

M134180 477

4

AUG 29 2016

DQA: _____ Date: _____




WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					



D4635-044 RH, AFT CEILING PANEL ASSY

ITEM	QTY -044	P/N	DESCRIPTION
1	X	D4635-044	RH, AFT CEILING PANEL ASSY
2	1	D4635-144	RH, AFT CEILING REPLACEMENT PANEL ASSY
3	1	D4646-1	PLENUM CAP ASSEMBLY
4	1	D4652-3 (REF)	MOUNTING NUT (PART OF D4652-5)
5	1	D4652-5	AIR VALVE, 1.16 ID DISK TYPE
6	1	D4655-1	SPEAKER
7	1	D4708-9	LANYARD
8	1	D4728-046	RH SPEAKER #3 HARNESS ASSY
9	1	D4743-1	SPEAKER GRILL
10	4	MS21044-N08	NUT, SELF-LOCKING
11	3	MS21919WDG8	CLAMP
12	4	MS24693-BB51	SCREW, CSK 100°
13	4	NAS1149DN832J	WASHER

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER

NO 149147 MJS
16-07-20

RELEASED



2015 JAN 26

NOTES:

- 1) MATERIAL: N/A
- 2) FINISH: N/A
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: IDENTIFY PER QSI 044 6.4, ON SMOOTH SIDE
- 7) WEIGHT: 5.0 lbs
- 8) INSTALL D4728-046 WIRE HARNESS PER QSI 048
- 9) ON D4708-9 LANYARD OPEN TO Ø0.196 BOTH ENDS

APPROVED

DESIGN	RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	RF		
CHECKED	AK	DRAWING NO.	REV. F
MFG. APPR.	DL	D4635	SHEET 7 OF 18
APPROVED	HS	TITLE	SCALE
DE APPR.	DS	OUTBOARD CEILING PANELS	NTS
DATE	14.11.28	COPYRIGHT © 2012 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	



D4635-044 RH, AFT CEILING PANEL ASSY
AUXILIARY VIEW

RELEASED
2015 JAN 26 *q*

APPROVED

DESIGN	RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	RF		
CHECKED	AK	DRAWING NO. D4635	REV. F SHEET 8 OF 18
MFG. APPR.	DL	TITLE	SCALE
APPROVED	HS	OUTBOARD CEILING PANELS NTS	
DE APPR.	DS		
DATE	14.11.28	COPYRIGHT © 2012 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

Linda Lacelle

From: Linda Lacelle
Sent: Monday, May 11, 2015 12:59 PM
To: Nigel Forbes
Subject: FW: 139 Ceilings Deviation

All Mike G...

From: David Shepherd
Sent: May-11-15 12:58 PM
To: Nigel Forbes; Bill Beckett
Cc: Roberto Fuentes; Linda Lacelle; Mario Poulin; Daryl Leger; Harvey Siemens
Subject: RE: 139 Ceilings Deviation

Nigel/Bill,

Can you clarify what is going on here. About 6 months ago, Operations pushed Engineering to change the lights and air vents previous lights and air vents were waaaaaaay too expensive. Now we have 3 years supply of the old expensive parts. I'm cor

Regards,
David

From: Mario Poulin
Sent: May-11-15 10:53 AM
To: Daryl Leger; Harvey Siemens
Cc: Roberto Fuentes; David Shepherd; Linda Lacelle
Subject: RE: 139 Ceilings Deviation

No orders pending,

From: Daryl Leger
Sent: Monday, May 11, 2015 12:49 PM
To: Mario Poulin; Harvey Siemens
Cc: Roberto Fuentes; David Shepherd; Linda Lacelle
Subject: RE: 139 Ceilings Deviation

Harvey
Re: 139 Ceilings

We have old stock quantities of	D4652-1 air Valve	QTY 163. (enough old stock for 13 sets)	New Stock Qty. 0
Old stock quantity of	D4638-1 light	QTY 73. (enough old stock for 24 sets)	New Stock Qty. 0

We do not have any orders on hand for ceilings and I have no idea if there are any pending orders.
Please advise

Daryl

From: Mario Poulin
Sent: Monday, May 11, 2015 10:45 AM
To: Harvey Siemens; Daryl Leger

Cc: Roberto Fuentes; David Shepherd; Linda Lacelle
Subject: RE: 139 Ceilings Deviation

Harvey,

We have stock for about 3 years, Ok to keep some old ones in case, but we should be reducing inventory first.

Mario,

From: Harvey Siemens
Sent: Monday, May 11, 2015 10:18 AM
To: Daryl Leger
Cc: Roberto Fuentes; Mario Poulin; David Shepherd
Subject: RE: 139 Ceilings Deviation

Daryl,

I thought we were going to move to the new parts and not use up all the old stock in case somebody wanted/needed replace

Just a little curious, why we are going backwards??

HS

From: Daryl Leger
Sent: May-11-15 5:56 AM
To: Harvey Siemens
Cc: Roberto Fuentes; Mario Poulin
Subject: 139 Ceilings Deviation

Harvey

Can you please provide a standard email that we can use to make D4634-xxx panels at Rev. F until old stock parts are used up
We will also need same type document to produce D4635-xxx panels as per Rev. E until old stock parts are used up.
We will not use unmatched parts (old/new on same set panel) as old stock diminishes.

Daryl